

Project PI: H. C. Arora

Project Title: Structural Health Assessment and Suggestions of Remedial Measures for NIEPVD Buildings at Dehradun

Name of Client: Director NIEPVD 116-Rajpur Road, Dehradun
(Uttarakhand) 248 001

Objectives: Suggestions of Remedial Measures for NIEPVD Building at Dehradun