

Project PI: S. K. Singh

Project Title: Condition Assessment and Structural Stability of Block-3 Building at CGO Complex, Lodhi Road, New Delhi and Suggesting Remedial Measures

Name of Client: Executive Engineer, Central Public Works Department (CPWD) "U" Division, Block No. 11, 2nd Floor CGO Complex, Lodhi Road, New Delhi

Objectives: Condition Assessment of the Building Suggesting Rehabilitation & Strengthening measures technical advice