

**Project PI:** Debdutta Ghosh

**Project Title:** Assessment of Water Ingress in the Main Dome of the Taj Mahal, Uttar Pradesh.

**Name of Client:** Superintending Archaeologist Archaeological Survey of India Agra Circle, 22-The Mall Road, Agra.

**Objectives:** Detailed visual inspection Main Dome of Taj Mahal Review of available architectural and structural drawings Seepage/Crack/Defect identification Non-destructive evaluation at sample locations (Thermal Imaging / GPR) Suggestions on remedial measures in the main dome Report containing recommendations.